



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1994

MODEL Previa

ENGINE FAMILY

RTY242HGEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 2,102 VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1995

MODEL Previa

ENGINE FAMILY

5V242H1GJEK

DISPLACEMENT 2.4

SALES AREA

50S

VEHICLES AFFECTED IN DR: 18,047

VEHICLES AFFECTED IN VERR:

Shared?

NO

PROBLEM:

Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1996

MODEL Previa

ENGINE FAMILY

1TY2-12HGKEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 8,029 VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1550

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

10/23/2000

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1999

MODEL RX300

ENGINE FAMILY

KTYXV03.0GBE

DISPLACEMENT 3.0

SALES AREA 50S

VEHICLES AFFECTED IN DR: 100,000

VEHICLES AFFECTED IN VERR:

Shared? YES

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

The exhaust pipe may crack and make abnormal noise.

DTCs

NOTE: RESOLUTION



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1550

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

10/23/2000

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2000

MODEL RX300

ENGINE FAMILY

YTYXV03.0FFE

DISPLACEMENT 3.0

SALES AREA

50S

VEHICLES AFFECTED IN DR: 100,000

VEHICLES AFFECTED IN VERR:

Shared?

YES

PROBLEM:

Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

The exhaust pipe may crack and make abnormal noise.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1635

VERR EXPECTED? DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

D570-?

D570-20040223

DR LETTER DATE

03/23/2001

11/27/2001

02/23/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2001

MODEL RAV-4

ENGINE FAMILY

1TYXT02.0FFH

DISPLACEMENT 2.0

SALES AREA

CL(CA+NLEV

VEHICLES AFFECTED IN DR: 83,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

MIL illumination related to the catalytic converter (P0420/P0430). MIL illumination due to improper OBD logic and early deterioration of oxygen storage capacity of the catalytic converter. Toyota submitted Running Change 02-TR-23 and Field Fix 01-TF-12, 01-TF-14. The ECM of affected in-use vehicles will be replaced with a modified ECM by dealership under warranty. If necessary a modified catalytic converter will be replaced under warranty. The 6/26/06 letter specifies, "The ECM of affected in-use vehicles will be re-flashed with a modified ECM by the dealership under Special Service Campaign." Related Field Fix of the Highlander, 2.4L was attached.

DTCs

NOTE: RESOLUTION

Reviewed - no further action

11/27/01 letter updated this DR to by implementing R/C 01-TR-29.
6/26/06 letter updated this DR of DIR-20040223.



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2225

VERR EXPECTED? DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20040222

DR LETTER DATE

02/25/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2004

MODEL Prius

ENGINE FAMILY 4TYXV01.5MC1

DISPLACEMENT 1.5

SALES AREA 50S

VEHICLES AFFECTED IN DR: 14,400 VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Non-engine emissions are emitted from the catalyst binder and interfere with the rear oxygen sensor switching and can cause a larger than actual Oxygen Sensor Capacity (OSC) to be calculated. This OSC calculation results in a possible false rear O2 Sensor malfunction detection (P0136/P0138) and a MIL illumination. Toyota submitted Running Change 04-TR-20 and TSB EG018. Affected in-use vehicles will be driven with special driving pattern described in the TSB for quick "break-in" of the exhaust pipes by a Toyota dealership under warranty. On the production line, when triggered by the fuel rail air bleed command, the aging counter will set to zero and allow a relaxed detection criteria.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1635

VERR EXPECTED? DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

D570-?

D570-20040223

DR LETTER DATE

03/23/2001

11/27/2001

02/23/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2002

MODEL RAV-4

ENGINE FAMILY 2TYXT02.0FFH

DISPLACEMENT 2.0

SALES AREA CL(CA+NLEV

VEHICLES AFFECTED IN DR: 68,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

MIL illumination related to the catalytic converter (P0420/P0430). MIL illumination due to improper OBD logic and early deterioration of oxygen storage capacity of the catalytic converter. Toyota submitted Running Change 02-TR-23 and Field Fix 01-TF-12, 01-TF-14. The ECM of affected in-use vehicles will be replaced with a modified ECM by dealership under warranty. If necessary a modified catalytic converter will be replaced under warranty. The 6/26/06 letter specifies, "The ECM of affected in-use vehicles will be re-flashed with a modified ECM by the dealership under Special Service Campaign." Related Field Fix of the Highlander, 2.4L was attached.

DTCs

RESOLUTION
NOTE:

Reviewed - no further action

11/27/01 letter updated this DR to by implementing R/C 01-TR-29.
6/26/06 letter updated this DR of DIR-20040223.



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2294

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20040623

DR LETTER DATE

06/23/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2000

MODEL Tundra

ENGINE FAMILY YTYXT04.7XBV

DISPLACEMENT 4.7

SALES AREA 50S

VEHICLES AFFECTED IN DR: 89,600

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

A crack can occur very close to the exhaust port of the cylinder. A revised manufacturing process to insure improved temperature control during fabrication of the exhaust manifold. A new improved exhaust manifold will be installed under warranty at a Toyota or LEXUS dealership.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2294

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20040623

DR LETTER DATE

06/23/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2000

MODEL Tundra

ENGINE FAMILY YTYXT04.7GXW

DISPLACEMENT 4.7

SALES AREA 50S

VEHICLES AFFECTED IN DR: 24,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

A crack can occur very close to the exhaust port of the cylinder. A revised manufacturing process to insure improved temperature control during fabrication of the exhaust manifold. A new improved exhaust manifold will be installed under warranty at a Toyota or LEXUS dealership.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2294

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20040623

DR LETTER DATE

06/23/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2001

MODEL Tundra

ENGINE FAMILY

1TYXT04.7FEBY

DISPLACEMENT 4.7

SALES AREA 50S

VEHICLES AFFECTED IN DR: 17,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

A crack can occur very close to the exhaust port of the cylinder. A revised manufacturing process to insure improved temperature control during fabrication of the exhaust manifold. A new improved exhaust manifold will be installed under warranty at a Toyota or LEXUS dealership.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2294

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20040623

DR LETTER DATE

06/23/2004

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2001

MODEL Tundra

ENGINE FAMILY 1TYXT04.7XBX

DISPLACEMENT 4.7

SALES AREA 50S

VEHICLES AFFECTED IN DR: 51,500

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

A crack can occur very close to the exhaust port of the cylinder. A revised manufacturing process to insure improved temperature control during fabrication of the exhaust manifold. A new improved exhaust manifold will be installed under warranty at a Toyota or LEXUS dealership.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2516

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050323

DR LETTER DATE

03/23/2005

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2000

MODEL Celica

ENGINE FAMILY

YTYXV01.8DDB

DISPLACEMENT 1.8

SALES AREA

CL(CA+NLEV

VEHICLES AFFECTED IN DR: 38,200

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

During deceleration under light load conditions, the catalytic converter will deteriorate and signal a MIL. A running change has been submitted and the catalytic converter will be replaced by dealerships under warranty.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2516

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050323

DR LETTER DATE

03/23/2005

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2001

MODEL Celica

ENGINE FAMILY

1TYXV01.8DDDB

DISPLACEMENT 1.8

SALES AREA

CL(CA+NLEV

VEHICLES AFFECTED IN DR: 27,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

During deceleration under light load conditions, the catalytic converter will deteriorate and signal a MIL. A running change has been submitted and the catalytic converter will be replaced by dealerships under warranty.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2516

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050323

DR LETTER DATE

03/23/2005

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2002

MODEL Celica

ENGINE FAMILY

2TYXV01.8FFB

DISPLACEMENT 1.8

SALES AREA

VEHICLES AFFECTED IN DR: 20,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

During deceleration under light load conditions, the catalytic converter will deteriorate and signal a MIL. A running change has been submitted and the catalytic converter will be replaced by dealerships under warranty.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2516

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050323

DR LETTER DATE

03/23/2005

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2003

MODEL Celica

ENGINE FAMILY 3TYXV01.8FFB

DISPLACEMENT 1.8

SALES AREA CL(CA+NLEV

VEHICLES AFFECTED IN DR: 14,500

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

During deceleration under light load conditions, the catalytic converter will deteriorate and signal a MIL. A running change has been submitted and the catalytic converter will be replaced by dealerships under warranty.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2516

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050323

DR LETTER DATE

03/23/2005

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2005

MODEL Celica

ENGINE FAMILY 4TYXV01.8VMC

DISPLACEMENT 1.8

SALES AREA CA

VEHICLES AFFECTED IN DR: 6,600 VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

During deceleration under light load conditions, the catalytic converter will deteriorate and signal a MIL. A running change has been submitted and the catalytic converter will be replaced by dealerships under warranty.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2516

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050323

DR LETTER DATE

03/23/2005

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2005

MODEL Celica

ENGINE FAMILY

5TYXV01.8VMB

DISPLACEMENT 1.8

SALES AREA

CA

VEHICLES AFFECTED IN DR: 3,300

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

During deceleration under light load conditions, the catalytic converter will deteriorate and signal a MIL. A running change has been submitted and the catalytic converter will be replaced by dealerships under warranty.

DTCs

NOTE: RESOLUTION

Reviewed - no further action



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 2517

VERR EXPECTED? DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-20050324

D570-20050324

D570-20050324

DR LETTER DATE

03/23/2005

06/26/2006

09/06/2006

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 2002

MODEL Highlander

ENGINE FAMILY 2TYXT02.4FFP

DISPLACEMENT 2.4

SALES AREA CL(CA+NLEV

VEHICLES AFFECTED IN DR: 19,500

VEHICLES AFFECTED IN VERR:

Shared? No

PROBLEM: Defective/Incorrect Exhaust System

TSB #

MIL illumination due to catalytic converter (P0420/P0430) due to improper OBD logic and early deterioration of oxygen storage capacity of the catalytic converter.

Remedy: The ECM of affected in-use vehicles will be re-flashed with a modified ECM by the dealership under Special Service Campaign. Previously submitted related Field Fix 02-TF-36 is attached. The impact on emission is under investigation and TSB EG041-45 has been issued. TSB EG006-13 is obsolete.

DTCs

Questions for manufacturer

NOTE: RESOLUTION

6/26/06 letter updated this DR of DIR-20050324. Field files submitted to CARB (TTC-05089) and EPA (TTC-05090) as of 6/14/2006.



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1994

MODEL Previa

ENGINE FAMILY

RTY242HGEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 2,102 VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1995

MODEL Previa

ENGINE FAMILY

5YF242H1GJEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 18,047

VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

NOTE: RESOLUTION



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1996

MODEL Previa

ENGINE FAMILY

1TY2-42HGKEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 8,029 VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1994

MODEL Previa

ENGINE FAMILY

RTY242HGEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 2,102 VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

NOTE: RESOLUTION



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1995

MODEL Previa

ENGINE FAMILY

5YF242H1GJEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 18,047

VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

NOTE: RESOLUTION



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1996

MODEL Previa

ENGINE FAMILY

1TY2-12HGKEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR: 8,029 VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1994

MODEL Previa

ENGINE FAMILY

RTY242HGEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR:

VEHICLES AFFECTED IN VERR:

Shared?

NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

NOTE: RESOLUTION



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1995

MODEL Previa

ENGINE FAMILY

5V242H1GJEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR:

VEHICLES AFFECTED IN VERR:

Shared? NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE:



Environmental Protection Agency
Office of Transportation and Air Quality

Defect Report and Voluntary Emission Recall Report Database

EPA NUMBER 1057

VERR EXPECTED?

DR Checklist Submitted:

RECORD TYPE DR

VERR Checklist Submitted:

MANUFACTURER ID TOYOTA/LEXUS

M/ATV EPA#

INITIALS

DR CAMPAIGN NUMBER

D570-?

DR LETTER DATE

12/09/1996

VERR CAMPAIGN NUMBER

VERR LETTER DATE

OWNER NOTIFY DATE

?

Recall or VSC?

Safety Recall?

H'way Motorcycle?

MODEL YEAR 1996

MODEL Previa

ENGINE FAMILY

1TY2-12HGKEK

DISPLACEMENT 2.4

SALES AREA 50S

VEHICLES AFFECTED IN DR:

VEHICLES AFFECTED IN VERR:

Shared?

NO

PROBLEM: Defective/Incorrect Exhaust System

TSB #

DESCRIPTION:

Thermal fatigue fracture on inner braid portion of the front exhaust pipe assembly due to insufficient welding.

DTCs

RESOLUTION
NOTE: